


**APPENDIX B:
MONITORING DATA**


Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-2 Total Phosphorus



Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-3 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-5 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-9 Total Phosphorus




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-2 Nitrate and Total Ammonia Nitrogen




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-3 Nitrate and TAN



Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-4 Nitrate and TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-7 Nitrate and TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-9 Nitrate and TAN


● Nitrate ● TAN




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-2 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-3 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring BV SI-4 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-5 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-7 Chloride




Bayshore Village Effluent Spray Irrigation Groundwater Quality Monitoring
BV SI-9 Chloride




Bayshore Village Effluent Spray Irrigation Wainman's Creek Water Quality Monitoring Total Phosphorus



Bayshore Village Effluent Spray Irrigation Wainman's Creek Water Quality Monitoring Unionized Ammonia



Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
North Field Lower - Total Phosphorus



Bayshore Village Effluent Spray Irrigation Soil Quality Monitoring
South Field - Total Phosphorus

